

Attachment A. Test Pit Logs




- GG1-1 ML SILT, clayey, slightly moist, Munsell color 10YR3/3, dark brown.
- GG1-2 CL CLAY, silty, moist, slightly plastic, some mottling, Munsell color 10YR4/4, dark yellowish brown.
- GG1-3 CL CLAY, minor silt, Munsell color 10YR4/4, dark yellowish brown.




distance in feet

- GG3-1 ML SILT, clayey, slightly moist, crumbly, Munsell color 10YR3/3, dark brown.
- GG3-2 ML SILT, clayey, Munsell color 10YR4/4, dark yellowish brown.
- GG3-3 CL CLAY, silty, moist, slightly plastic, Munsell color 10YR4/4, dark yellowish brown.



distance in feet

- GG2-1 ML SILT, clayey, slightly moist, Munsell color 10YR4/2, dark grayish
- GG2-2 CL CLAY, silty, moist, slightly plastic, Munsell color 10YR4/4, dark yellowish
- GG2-3 CL CLAY, silty, moist, slightly plastic, Munsell color 10YR4/4, dark yellowish brown.



distance in feet

- GG4-1 CL CLAY, silty, moist, Munsell color 10YR4/2, dark grayish brown.
- GG4-2 CL CLAY, silty, very moist to wet Munsell color 10YR3/4, dark yellowish brown.

LEGEND

- CL Soil symbols used are from the "Unified Soil Classification System"
- GG1-1 Soil and/or bedrock sample number.
 Sample number is located at depth taken in cross section.
- Contact between different materials within same geologic unit.




Water table.

NOTES: Trench locations shown on Figure 6

All trenches were dug using a Mitsubishi hydraulic excavator.


STATE OF CALIFORNIA
THE RESOURCE AGENCY
DEPARTMENT OF WATER RESOUCES
NORTHERN DISTRICT

THE SITES AND COLUSA PROJECTS CONSTRUCTION MATERIALS




GG5-1 CL CLAY, slity, slightly moist, stiff, Munsell color 10YR3/3, very dark brown.

GG5-2 CL CLAY, silty, moist, slightly plastic, some mottling, Munsell color 10YR4/4, dark yellowish brown.



GG6-1 CL CLAY, silty, slightly moist, tough, Munsell color 10YR3/2, very dark graylsh brown.




distance in feet

GG7—1 ML SILT, clayey, slightly moist, crumbly, Munsell color 10YR3/2, very dark grayish brown.

GG7-2 ML SILT, clayey, Munsell color 10YR4/4, dark yellowish brown.

GG7—3 CL CLAY, silty, moist, slightly plastic, Munsell color 10YR4/4, dark yellowish brown.



distance in feet

GG8-1 CL CLAY, silty, gravel clasts — fine to medium, Munsell color 10YR4/2, dark grayish brown.

GG8-2 Weathered bedrock — mudstone, crumbly.

LEGEND

CL Soil symbols used are from the "unified Soil Classification system"

GG5-1 Soil and/or bedrock sample number.
Sample number is located at depth taken in cross section.

Contact between different materials within same geologic unit.

Contact between different geologic units.

 $\underline{\nabla}$


Water table.

NOTES: Trench locations shown on Figure 6


All trenches were dug using a Mitsubishi hydraulic excavator.

STATE OF CALIFORNIA
THE RESOURCE AGENCY
DEPARTMENT OF WATER RESOUCES
NORTHERN DISTRICT

THE SITES AND COLUSA PROJECTS
CONSTRUCTION MATERIALS




- SC4-1 ML SILT, clayey, slightly moist, Munsell color 10YR3/3, very dark brown.
- SC4-2 CL CLAY, silty, Munsell color 10YR3/6, dark yellowish brown.
- SC4-3 CL CLAY, minor silt, slightly plastic, moist, Munsell color 10YR3/2, very dark grayish brown.




distance in feet

- SC6-1 CL CLAY, minor silt and gravel, Munsell color 10YR3/2, very dark grayish brown.
- SC6-2 CL CLAY, minor gravel, Munsell color 10YR4/4, dark yellowish brown.
- SC6-3 CL CLAY, clayey gravel with minor sand, gravels are subrounded black chert and red sandstone, Munsell color 7.5YR5/4, brown.



distance in feet

- SC5-1 CL CLAY, minor silt, Munsell color 10YR3/1, very dark gray.
- SC5-2 CL CLAY, very minor silt, medium plastic, wet below ten feet, Munsell color 10YR3/3, dark brown.



distance in feet


- SC7-1 CL CLAY, silty, few sand grains, Munsell color 10YR4/2, dark grayish brown.
- SC7-2 CL CLAY, minor silt, scattered fine gravel clasts, gastropod shell, Munsell color 10YR6/6, bownish yellow.

LEGEND

- CL Soil symbols used are from the "Unified Soil Classification System"
- SC4-1 Soil and/or bedrock sample number. Sample number is located at depth taken in cross section.
- Contact between different materials within same geologic unit.
- Contact between different geologic units.
 - ____ Water table.
- NOTES: Trench locations shown on Figure 5
 - All trenches were dug using a Mitsubishi hydraulic excavator.

STATE OF CALIFORNIA
THE RESOURCE AGENCY
DEPARTMENT OF WATER RESOUCES
NORTHERN DISTRICT


THE SITES AND COLUSA PROJECTS CONSTRUCTION MATERIALS



SC8-1 ML SILT, clayey, minor gravel, gravel lens in side wall, Munsell color 10YR3/3, very dark brown.

SC8-2 SM CLAY, silty, with sand and gravel -angular, Munsell color 7.5YR5/4, brown.

SC8-3 CL CLAY, gravelly, rounded clasts up to cobble in size, Munsell color 10YR5/8 to 7.5YR5/8, yellowish brown to strong brown.




distance in feet

SC10-1 CL SILT, clayey, Munsell color 10YR3/4, dark yellowish brown.

SC10-2 CL CLAY, silty, Munsell color 10YR4/6, dark yellowish brown.

SC10-3 GC GRAVEL, clayey, Munsell color 10YR4/4, dark yellowish brown.



distance in feet

SC9-1 CL CLAY, minor silt, slightly moist. calcareous streaking, Munsell color 2.5YR4/3, reddish brown.

SC9-2 CL CLAY, moist, plastic some black mottling, Munsell color 2.5YR4/2, weak red.

Possible bedrock at 12 feet?

LEGEND

CL Soil symbols used are from the "Unified Soil Classification System"

SC9-1 Soil and/or bedrock sample number. Sample number is located at depth taken in cross section.

— Contact between different materials within same geologic unit.

Contact between different geologic units.

 $\underline{\underline{\nabla}}$

Water table.

NOTES: Trench locations shown on Figure 5

All trenches were dug using a Mitsubishi hydraulic excavator.

STATE OF CALIFORNIA
THE RESOURCE AGENCY
DEPARTMENT OF WATER RESOUCES
NORTHERN DISTRICT

THE SITES AND COLUSA PROJECTS CONSTRUCTION MATERIALS

Attachment B. Laboratory Results

STATE OF CALIFORNIA THE RESOURCES AGENCY DEPARTMENT OF WATER RESOURCES

CLASSIFICATION TEST SUMMARY

DIVISION OF ENGINEERING CIVIL ENGINEERING CANALS AND LEVEES SECTION

PROJECT:

Sites and Golden Gate Dams

FEATURE: Proposed Geologic Exploration for Borrow Material

											NT FIN	ER											
			· · ·			1944 X-1	***	HANICA	L ANAL	YSIS					нч	OROME	TER	ATTER	RBERG	SPEC.			CLASSIFICATION
LAB.	HOLE	F.S.			·	GRAVE					SA	DO			SI	T&a	AY	LIM	ıms	GRAV.	ORG COOL		
NO.	NO.	МО	6"	3*	11/2"	,/4	3/6"	4	8	16	30	50	100	200	5M	2M	1M	L.L.	P.I.	-#4	*	GROUP SYMBOL	GROUP NAME
97-157	SC-1	1										100	98	93				45	27	2.78	4.7		
97-158	•	2				100	99	99	97	96	95	91	81	70				38	23	2.79		CL	Lean clay
97-159	SC-2	1					0.0			100	99	97	80	61				34	17		3.6	CL	Sandy lean clay
97-160	•	2						100	96	93	92	91	90	87				-	-	-	3.7	CL	Sandy lean clay
97-161	SC-3	1						100	99	97	94	92	90	86				48	31	-	4.4	CL	Lean clay
97-162	•	2						100	94	89	86	83	81	79			· ·	51	35	-	4.9	СН	Fat clay
97-163	LC-1	1						100	100	99	98							53	34	-	5.0	CH	Fat clay with sand
97-164	•	2	-						100			91	75	61				33	17	2.77	3.7	CL	Sandy lean clay
97-165	LC-2	1		-					100	99	99	98 99	96	92				44	25	2.83	3.8	CL	Lean clay
97-166	•	2							100				95	88	- to			44	29	-	4.4	CL	Lean clay
97-167	GG-I	1							100	99	97	92	84	75	1			34	17	-	3.1	CL	Lean clay with sand
97-168		2			-			100			100	99	93	74				32	16	2.78	4	CL	Lean clay with sand
97-169		3						100	98	96	94	92	88	81				44	29	2.80	5.1	CL	Lean clay with sand
97-170	GG-2	1						100	100	99	99	97	94	85				41	25	-	5	CL	Lean clay with sand
97-171		2						100	99	99	98	96	87	67				30	13	-	3.8	CL	Sandy lean clay
97-172	•	3	-	-		100	00		98	97	96	94	86	68				36	18	-	4	CL	Sandy lean clay
97-173		4	-			100	99	99	99	98	97	95	91	86				59	43	-	7.2	CH	Fat clay
								100	99	96	93	88	84	76				45	30	-	6.1	CL	Lean clay with sand
				-																			
				-																			
•																							
									·														
	لبا		<u> </u>	L																			

DATE:	6/3/98	REMARKS:		Sheet 1 of 1
INITIAL:	RGJ		IM - INSUFFICIENT MATERIAL	
REQUEST NO .:	98-18	9	NP - NON-PLASTIC	
			NG - NO GOOD	

STATE OF CALIFORNIA THE RESOURCES AGENCY DEPARTMENT OF WATER RESOURCES

SANDSTONE TEST SUMMARY

DIVISION OF ENGINEERING CIVIL ENGINEERING CANALS AND LEVEES SECTION

PROJECT:

Sites and Golden Gate Dams

FEATURE Sandstone Quality for Rip-Rap and RCC Aggregate

							PERCE					,		3-inch (CUBE SAN	MPLES		
LAB.	HOLE						HANK	U. ANA	LYSIS					compressive	specific	percent		CLASSIFICATION
NO.	NO.	F.S. NO.		-	GRAVE					SA	WD			strength	gravity	absorption	GROUP	
	110.	NO.	3"	17,-	3/4"	3/6"	4	8	16	30	50	100	200	(psi)	(ssd)	*	SYMBOL	GROUP NAME
98-174	SSQ-1	Α	<u> </u>	-	<u> </u>	-				-	-	ļ						
•		В	-	 		-	 				<u> </u>	ļ		11130	2.50	2.6		
•	•	C	-	-		-					├	<u> </u>		9960	2.48	2.6		
98-175	SSQ-2	A		 		 					ļ	ļ		10830	2.48	2.8		
•		В	-			-		ļ						11840	2.50	2.5		
•		C				-			<u> </u>					11690	2.50	2.5		
98-176	SSQ-3	A		-		-								12370	2.49	2.6		
30-170	33Q-3	В												•	•	•		
		C											7	•		•		
98-177	SSQ-4	-			· .								- "	•	•	•		
•	350-4	A				-							-	11830	2.50	2.4		
•		В											j	11630	2.50	2.5		
98-178		С												**	**	**		
90-176	SSQ-5	A												10160	2.46	3		
		В		-										10200	2.45	2.8		
98-179	SSQ-6	C			<u> </u>									10820	2.45	2.8		
30-179	55Q-6	A												9940	2.45	2.8		
•		В												9910	2.45	2.9		
98-180		С		-										10990	2.45	2.9		
90-100	SSQ-7	A												11220	2.52	2.5		
		В												10320	2.51	2.3		
		С												10740	2.50	2.7		
98-181	SSQ-8	A												12690	2.48	2.7		
	-:-	В												12130	2.49	2.5		
		С									-			12060	2.49	2.4		

5/25/1998
RG
98-18

REMARKS: * Unable to obtain cube sample. One side of slab is fractured and uneven.

** can only secure two cube specimens from slab.

Sheet 1 of 2

IM - INSUFFICIENT MATERIAL

NP - NON-PLASTIC

NG - NO GOOD

STATE OF CALIFORNIA THE RESOURCES AGENCY DEPARTMENT OF WATER RESOURCES

SANDSTONE TEST SUMMARY

DIVISION OF ENGINEERING CIVIL ENGINEERING CANALS AND LEVEES SECTION

PROJECT:

Sites and Golden Gate Dams

FEATURE Sandstone Quality for Rip-Rap and RCC Aggregate

							PERCE	NT FIN	ER					3-Inch (UBE SAN	PIES		
						MEC	HANICA	L ANA	LYSIS					compressive	specific	percent		CLARCITICATION
LAB.	HOLE	F.S.			GRAVE					SA	ND			strength	gravity	absorption		CLASSIFICATION
NO.	NO.	NO.	3*	11/2"	3/4"	3/6"	4	8	16	30	50	100	200	(psi)	(ssd)	*	GROUP SYMBOL	GROUP NAME
98-182	SSQ-9	A	-	-	-	-												
•	•	В	-	-	-	-								11250	2.49	2.8		
•	1	C	-	+	-	-	-							11040	2.49	2.6		
98-183	SSQ-10	A	-	-		-								11360	2.48	2.6		
•	100010	B	-	+		-							-	11240	2.45	2.8		
•	1.	C			-	-								10970	2.46	2.7		
	 					-								11490	2.46	2.7		
						-											-	
			-			<u></u>							,					
				-	RE	SULTS	SOFC)UALI	TY TES	STSO	N CRI	USHE	DSAN	DSTONE				
													7					
			1. A	SIMC	-131 L	os Ang	geles I	Rattler	Test (Gradi	ing A	$= 1^{1}/_{2}$	x 3/8 s	ize fraction)	:			
			<u> </u>		100 16	evoluti	ons =	11.4 p	ercen	t loss								
					500 re	evoluti	ons =	43.4 p	ercen	t loss								
				Spec	ific Gr	avity o	md Al	sorpt	on tes	ts befo	ore pe	erform	ing LA	RT				
					Spec	. Grav	. = 2.4	8			•			-				
							= 4.2		ent				-)
,										-								
			2. AS	TMC	Du	rabilit	y Inde	x (3/4	x #4 e	70 fm	tion	•				.		
					Dural	bility Ir	ndex, I)c = 4	2		4011)							
								-	-					-				
				Speci	fic Gr	mity o	and AL					لبا						
				Specific Gravity and Absorption tests befo Spec. Grav. = 2.50								riorm	ing Co	arse Durabil	ity Index			
				Absorption = 4.1 percent														

DATE	5/25/1998
INITIAL	RGJ
REQUEST NO	98-18

REMARKS: In determining the absorption, the strength samples (cubes) were oven dried at 160 °F. The crushed samples were oven dried at 230 °F. All samples were soaked for 24 hours.

Sheet 2 of 2

IM - INSUFFICIENT MATERIAL

NP - NON-PLASTIC

NG - NO GOOD

CLASSIFICATION TEST SUMMARY

FEATURE:

DIVISION OF ENGINEERING CIVIL ENGLISHERING CANALS AND LEVEES SECTION

STATE OF CALIFORNIA

	SINIC C. C.
١	THE RESOURCES AGENCY
•	
•	DEPARTMENT OF WATER RESCURCES

PROJECT: Sites Dam PERCENT FINER PERCENT MOSTURE HOROWETER KTRERBERG MECHANICAL ANALYSIS GROUP CLASSIFY ATION CONTENT ORGANIC I IMITS TA CLAY SAND SYMBOX GROUP NAME GRAVEL DEPTH , A * * 5m 2m 100 FS LAB HOLE 8 16 30 3/4" 3/8" man dan a NO NO (text) NO . SHAFT CHAP a 96-737 SC-4 Fet clay ai ? 32-731 azo clas a SE 13 Fat day ан SC-5 35 740 ä Lean clay with sand a 99.74 Fat duy with sand œ G 99.740 SC3 Sandy loan ckey a 99-743 au Fut clay di દા 98 744 Loan ciny with sound a SC 7 DH-140 a Lean clay with sand 00.74 SONLY IOUR CHES a 28-74 SC-8 Chayey sand a 99-74 Fat clay CH 99-749 QT. CH. Fat clay SCO 99-750 G7 Lean clay with sand ū 99-75 ā Loss ctur with sound Di-752 SC-10 Clayey sand with grand a 96 753 AND CHAP a 99 754 a 4. GG-I 89.755 ean day a BA-150 a Leanchy with sand 99.757 ā Lean day with sand 66.5 89-758 Launcher with sand a 99.75 Leantiley with sand a 90-TO LO: Soudy bean chay a GG-3 SQ-781 a Lean day with sand 99.760 - CHY • 99-768 Lair char CI. ¥ 96-764 GG4 . CH Fat cay . 99-785 Sandy lean stay CL 96-768 Fat clay CH HQ 76/ Loan clay CL 90-78 GG-8 Lean day with sand CL GG7 £ 99.70 <u>\$6</u> CL Lean clay with sard 99-7X Fat day with want CH 99-771 a Lean day GG-8 94-772 #2 H. ¥715

			· · · · · · · · · · · · · · · · · · ·
	14700	REMARKS:	
DATE	3/17/09	.,	
MITAL:			
	2: 25		
RECUEST NO	99-35		

IM - INSUFFICIENT MATERIAL

NP - NON-PLASTIC NG - NO GOOD

Feetumer 9025 XI S

Page 1

a better copy from

STATE OF CALFORNIA THE RESOLUCES AGENCY DEPARIMENT OF WATER RESOLUCES

SACIU. MHINI. THRD

CLASSIFICATION TEST SUMMARY

FEATURE: Composito Samples


DIVISION OF BUGINEERING CIAL ENGNEERING CANALS AND LEVEES SECTION

Page 1 of 1

ROJEC		Sitos D												CXAUL								
		1111		Carrer	711.79	111771	nii ii			PERCE	T FINL											LI ASSECTION (INC.)
					*	****	MEC	HANK	LWAL	Y515					H	CHOM	IHK .	AUTH	W HG	WOMEN HIGH		
				131711	77.10	CRAVE					SN	VO.		****		*14C	AY	316	13.	CONTENT ONEMES	CHATTA	11.53
NO.	NO.	NO.	[feet]	S.C	15*	344	3/8			14	30	50	400	440	544)	244	140	(L)	i ex		SYMBOL	GACGPIONE
								100	99	98	97	97	94	83	41		27	38	_	3.9	C.	Lean clay w/sand
9 1419	GG · San	nples						tan	99	30	3,					 -					•	
								100	97	96	95	93	89	81	48	38	33	45	30	4.2	a	Lean clay w/sand
9-1420	SC-San	rbles	ļ					100	9,	30	- 30			-		1		i	1	İ	į.	
					ļ											:			 		<u>; </u>	
					<u> </u>				-		 			-	-		 		 		i	
				!	!			<u>;</u>		-	+			├			 	-	i ·			1
				<u> </u>	:	<u> </u>	-		 		!			-			+	 	-	 	:	
					:	<u> </u>	<u> </u>			-					├	.	-	-	-			
							ļ	<u> </u>	<u> </u>	-				-	1		+	-		-	i	:
		<u>:</u>	_	·	<u>:</u>		ļ		1-	 			:							 	:	•
	i	!		-					-	 	÷			+	1		+	-	!	 		
					-	!	-		-			:		+	+		+	-		 		
						:	<u> </u>		-	<u>:</u>		-		+		-	+	-	+-	<u> </u>		
							1		-	-		<u>: </u>		+		-	+	+-	$\dot{-}$	 		
								<u>:</u>	1.	<u> </u>		<u>:</u>			-	\dotplus		-	+		-	

	9/28/99 REMARA	99-1419. Specific Gravity - 274; 14cz. Dry Density - 111.8pct; Opt. Moist - 17.4%	W-INSUFFICIENT MATERIAL
ATE:		93-1420: Specific Gravity - 2.74: Max. Dry Density - 110. Opcf: Opt. Moist 17.0%	NP-HON-PLASTIC
MITAL.	dnt	95-1421 ober in Citati, and the second	NG - NO GOOD
EQUEST N	99-51		

Attachment C. Terrace Descriptions



This page deliberately left blank.

Terrace Descriptions

Station Number	Depth	Description	USCS	Color Munsell
3-15-1	0-2	SILT, clayey, brown	ML	
	2-6 6-7	CLAY, silty lighter brown GRAVEL, clay matrix, clasts rounded chert	CL GC	
3-15-2	0-4 4-10	SILT, clayey GRAVEL, silty, clasts are subangular sst.	ML GM	
3-15-3	0-2 2-4	SILT, clayey, minor rounded, fine gravel clasts of red and black chert SILT with clay and sand to granule above silty gravel w/ rnd chert clasts 3-4in.	ML ML	10YR3/4 10YR4/3
3-15-4		Boxer Fm at surface		
3-15-5	0-2	SILT, clayey with gravel clasts to 3 in	ML	10YR4/4
3-15-6	0-4	Thin terrace overlying Boxer		
3-15-7	0-2 9-11	CLAY, silty, no gravel CLAY, plastic	CL CL	10YR4/2 10YR5/4
3-15-8	0-15	Clayey silt and silty clay, some gravel lenses to 4 ft., 2+ft clay at base		
3-17-1	0-4 8-10	SILT, clayey CLAY, plastic	ML CL	
3-17-2	0-3 3-9 9-12	SILT, clayey CLAY, silty CLAY, plastic	ML CL CL	10YR4/2 10YR4/4 10YR5/4
3-17-3	0-3 12-15	SILT, clayey CLAY, plastic	ML CL	
3-17-4	0-5	Terrace deposit above Boxer FM.		
3-17-5	0-12	Flat lying clay bed bottom 2ft of terrace		
3-17-6	0-5	SILT, clayey, with gravel, clasts large, subangular sst., no soil structure	ML	7.5YR4/2
3-17-7	0-1.5	CLAY, silty with angular mudstone fragments overlying Boxer Fm.	CL	7.5YR4/4
3-17-8	0-5 5-10 10-20	SILT, clayey CLAY. Silty ??	ML CL	10YR4/3 10YR4/4
3-17-9	0-6	Six feet of terrace deposit overlying Boxer Fm.		

Note: Station Number is keyed to the flight line and photo number

Station Number	Depth	Description	USCS	Color Munsell
3-17-10	0-4 4-9	SILT, clayey GRAVEL, clayey, silty, sandstone clasts Just upstream, reddish silty clay at base under gravel lens (buried soil)	ML GC	7.5YR4/4
3-17-11	9-11.5	Buried soil under gravel lens, SILT, fine sandy clayey	ML	7.5YR4/6
3-17-12	0-5	Upper sloped surface, 5 ft. thick overlying Boxer Fm. Low, flat terrace, blocky prismatic soil structure, no Boxer at base		7.5YR4/3 10YR4/2
3-17-13	0-? Not expos ed	Upper sloped surface, CLAY, silty with rounded clasts, fine to medium	CL	7.5YR4/4
3-19-1	0-2.5	Thin soil overlying Boxer Fm		
3-19-2	0-2.5	Thin soil overlying Boxer Fm, bedding planes juxtaposed		
3-19-3	0	Boxer exposed at surface		
3-19-4	0-6.5	SILT, clayey at surface grading to silty clay	ML	
3-19-5	0-8	CLAY, gravelly, silty, clasts rounded to 4 inches red and black chert	CL	7.5YR4/4
3-15-1	0-2 2-6 6-7	SILT, clayey, brown CLAY, silty lighter brown GRAVEL, clay matrix, clasts rounded chert	ML CL GC	
4-13-2	0-3 3-9 9-12	SILT, clayey, blocky-prismatic structure, crumbles easily Clay, silty to clayey silt, CLAY, silty with fine gravel clasts overlying Boxer Fm. Buried soil in opposite bank	ML CL CL	10YR3/3 10YR4/3 10YR5/4 7.5YR4/4
4-13-3		Cemented gravel bed overlying Boxer Fm.		
4-13-4	0-4 4-6	SILT, minor clay, few fine gravel clasts, inset lower terrace GRAVEL, clayey, silty matrix, clasts fine to medium	ML GC	10YR4/3
4-13-5	0-3	CLAY, silty over Boxer Fm.	CL	7.5YR4/4
4-13-6		Possible Tehama Fm. on hillside, clayey silt matrix with scattered clasts		10YR6/4
4-13-7	10-12	Possible buried soil between terrace deposit and Boxer Fm., CLAY with rounded gravel clasts	CL	7.5YR4/3
4-13-8	0-3	Thin soil overlying Boxer Fm, Note: Station Number is keyed to the flight line and photo number		

DRAFT

Station Number	Depth	Description	USCS	Color Munsell
4-15-1	0-15 15-25	typical terrace deposit GRAVEL, sandy loose, unconsolidated, rounded sst. Clasts, rusty staining minor clay	GC	5YR4/6
	25-30	CLAY, silty moist, soft moderately plastic	CL	5Y3/2
4-15-2		lower inset? Terrace with poor soil over buried soil, 7.5YR3/4 with orange mottles		
4-15-3	0-28 28-30	terrace deposit with very little structure Grey clay		10YR3/3
4-15-4	0-1 1-6	colluvium overlying terrace deposit CLAY, silty, hard, blocky, base not exposed	CL	10YR4/2
4-15-5		SILT, clayey, friable CLAY, silty, blocky with orange and grey mottling	ML CL	10YR4/4 10YR5/2
4-17-1	7-10	Flat lying conglomerate bed overlying Boxer, hard, cemented, medium to coarse clasts, rounded sandstone and chert, sandstone matrix	GW	
4-17-2	0-1 1-5	SILT, clayey CLAY, sandy, silty, with gravel. Buried soil	ML CL	10YR 3/3 7.5YR4/6
4-17-3	0-2 2-4 4-5	SILT, clayey, minor fine gravel CLAY, silty CLAY, minor silt	ML CL CL	10YR3/2 10YR4/3 10YR4/2
4-17-4	0-17 17-20	Terrace Deposit CLAY, grey	СН	gley
4-17-5	0-7	Thin terrace over sandstone Boxer		
4-17-6		Terrace varies from 6 to 15 ft thick		
3-25-1	0-12	Channel gravels appear to be plated onto sidewalls		
3-25-2	0-3.5	SILT, clayey with minor fine gravel clasts	ML	10YR3/3
	3.5-7.5	CLAY, gravely, subrounded sst. clasts to 8 inches, overlying Boxer	CL	10YR5/6
3-25-3	0-3.5 3.5-8 8-11.5	SILT, clayey with minor fine gravel clasts CLAY, silty CLAY, minor silt, occaisional gravel clasts	ML CL CL	10YR4/3 10YR4/4 10YR4/3
3-25-4	0-5 5-7.5 7.5-10	SILT, clayey GRAVEL, clay matrix, fine to coarse, subrounded to rounded sst and chert Boxer	ML GC	10YR4/3 10YR5/6

Note: Station Number is keyed to the flight line and photo number

Station Number	Depth	Description	USCS	Color Munsell
3-27-1	0-2 2-6	SILT,very fine sand Silt with minor fine gravel, rounded chert clasts	ML	10YR5/6
3-27-2	0-1 1-6	SILT, clayey GRAVEL, clay matrix, fine to medium red and black chert, rounded	GC	7.5YR5/6
3-29-1	0-2 2-7	SILT, clayey SILT, clayey, limb at 3.5 ft	ML ML	10YR4/3 10YR3/2
3-29-2		SILT, clayey, with some granule sized clasts SILT, with fine to medium gravel clasts, CaCO3, bone fragment GRAVEL, silt matrix, medium to coarse, sandstone clasts subangular	ML ML GM	10YR3/2 10YR6/3 10YR4/3
3-29-3	0-6 6-8 8-11	SILT, clayey GRAVEL, silty, clayey, two lenses CLAY, plastic	ML GM CL	10YR3/3 10YR5/6
3-29-4	0-6	SILT, clayey with gravel lenses, sandstone bedrock at base	ML	
3-29-5	0-2 2-3 3-4.7 4.7-6	Clay, silty to clayey silt SILT, crumbly GRAVEL, silty, clasts fine to cobble, CaCO3 coatings CLAY, silty, stiff, Boxer sst and mst exposed in channel	CL ML GM CL	7.5YR3/2 10YR3/3 10YR5/6
3-29-6	0-2	CLAY, silty with rounded clasts of red and black chert and sst. Conc.	CL	7.5YR4/4
4-23-1	0-25	SILT, clayey with granule clasts of mudstone and sst, weathered	ML	7.5YR5/4
4-23-2	0-2.5 2.5-6.5	SILT, clayey CLAY, silty with minor clasts of sst. and claystone	ML CL	10YR3/2 10YR4/3
4-23-3	0-4	SILT with minor clay, mudstone bedrock in channel on high fan	ML	7.5YR 5/4
4-23-4	0-3.5	SILT, clayey with granule clasts of weathered sst, Boxer exposed in channel	ML	7.5YR4/3
4-23-5	0-1.5	Colluvium over lying vertical bedded Boxer		
4-29-1	0-6 6-9	SILT, clayey with some gravel, increasing downward, shale and sst. Clasts GRAVEL, clayey sandy matrix, subrounded to rounded red and black chert	ML GC	10YR4/3 10YR4/3
4-29-2	0-4	CLAY, silty, with gravel clasts, upper sloped surface overlying Boxer	CL	7.5YR4/3
4-29-3	0-4 4-8 8-9.5	CLAY, silty CLAY, silty CLAY, buried soil	CL CL CL	10YR3/2 10YR5/4 7.5YR5/3
4-29-4	0-3	Thin terrace overlying Boxer Fm.		

Note: Station Number is keyed to the flight line and photo number

66 DRAFT

Station Number	Depth	Description	USCS	Color Munsell
4-29-5	0-5 5-8	SILT, clayey GRAVEL, clayey sandy matrix, subrounded to rounded chert, sst clasts at base Up channel Boxer is near surface, down channel Boxer is replaced by clay	ML GC	10YR4/3 7.5YR4/6 10YR5/4
4-29-6	0-12	Terrace 12 ft thick		
4-29-7		Upper sloped surface appears to plunge under the Low flat terrace and pinch out against the underlying Boxer Fm. USS is GRAVEL, clayey QLFT is SILT, clayey with blocky prismatic soil structure	GC ML	7.5YR4/6 10YR3/3
4-29-8	0-2	Colluvium overlying Boxer, sandstone clasts to 1+ ft.		10YR4/6
4-29-9	0-2.5	CLAY, minor silt over weathered Boxer	CL	10YR4/3
4-29-10	0-2.5 2.5-5	CLAY with minor silt Weathered claystone	CL	10YR3/3 10YR5/4
4-29-11	0-6 6-12	SILT, clayey CLAY with minor silt	ML CL	10YR3/4 10YR4/3
3-35-1	0-4 4-8	SILT, clayey, dark, blocky prismatic structure GRAVEL, sandy, clayey overlying Boxer Fm.	ML GC	
3-35-2	0-4 4-9	SILT, clayey, dark, blocky prismatic structure GRAVEL, clayey overlying west dipping Boxer	ML GC	10YR3/3 5YR4/4
3-35-3	0-6 6-10	SILT, clayey CLAY, silty with gravel	ML CL	10YR3/3 7.5YR4/4
3-35-4	0-4	CLAY, silty on surface of upper sloped surface, overlying Boxer Fm.	CL	7.5YR3/4
3-35-5		CLAY, silty with some gravel, upper sloped surface, cemented gravel breccia in channel	CL	7.5YR4/3
3-35-6	0-5	Typical QLFT deposit, overlying possible Tehama Fm.??		

Note: Station Number is keyed to the flight line and photo number